

Department of Veterans Affairs
Federal Supply Schedule
Authorized Federal Supply Schedule Price List

EFFECTIVE September 15, 2008

On-line access to contract ordering information, terms and conditions, up-to-date pricing, and the option to create an electronic delivery order, are available through *GSA Advantage!* a menu-driven database system. The INTERNET address for *GSA Advantage!* is: www.GSAAdvantage.gov.

Medical Equipment and Supplies
FSC Group 65, Part II Sections A
FSC Class 6510, 6515, 6530 and 6532

Contract No: V797P-4128b

Contract Period: 9/15/08 through 9/14/13

For more information on ordering from Federal Supply Schedules
Click on the FSS Schedules button at www.fss.gsa.gov.



C.A.R.E. Medical LLC
7939 Honeygo Blvd. Ste 118
White Marsh, MD 21236
(410) 933-2080
(410) 933-2084 Fax
www.caremedicalllc.com

Ms. Tammy Hall
President
thall@caremedicalllc.com

Size of Business: Small
TIN: **35-2301790**

CUSTOMER INFORMATION:

1. Table of awarded special item number(s) with appropriate cross-reference to page number(s):

SIN(s)

A-200

Page

3-6

2. Maximum order: **\$500,000**
3. Minimum order: **NONE**
4. Geographic coverage (delivery area): **50 States, D.C. and POE Puerto Rico**
5. Point(s) of production: **White Marsh, MD**
6. **Net Prices, Discounts Deducted.**
7. Quantity discounts: **None**
8. Prompt payment terms: **5% 10, Net 30 days**
- 9a. **Government commercial credit card accepted no additional discount.**
- 9b. Government commercial credit cards **are accepted** above the micro-purchase threshold.
10. Foreign items (list items by country of origin): **none**
- 11a. Time of delivery: **Within 3 -7 days, ARO**
- 11b. Expedited Delivery: **None.**
12. F.O.B. point(s): **50 States, D.C. and POE Puerto Rico**
- 13a. Ordering address: **7939 Honeygo Blvd. Ste 118, White Marsh, MD 21236**
- 13b. Ordering procedures: **For supplies and services, the ordering procedures, information on Blanket Purchase Agreements (BPA's), and a sample BPA can be found at the GSA/FSS Schedule homepage (fss.gsa.gov/schedules).**
14. Payment address: **7939 Honeygo Blvd. Ste 118, White Marsh MD 21236**
15. Warranty provision: **Government** standard warranty clauses 52.212.4(o)(p).
16. Return Goods Policy: **C.A.R.E. Medical policy dated 9/15/08.**

Obtain a Return Authorization Number by Phone

Contact Tammy Hall by phone at 410-933-2080 between 8:00 a.m. – 5:00 p.m. Eastern Standard Time, Monday through Friday, to obtain a Return Authorization Number.

Obtain a Return Authorization Number by E-Mail

Contact Tammy Hall via e-mail at thall@caremedicalllc.com to obtain a Return Authorization Number prior to returning any merchandise. Be sure to include your order number, account number and item number of the product(s) you'd like to return, as well as your contact information.

17. Data Universal Number System (DUNS) number: **807788141**
18. Notification regarding registration in Central Contractor Registration (CCR) database. **Yes**
19. Industrial Funding Fee: **Absorbed**

<i>SIN</i>	<i>Item# / Repair Code</i>	<i>Repair Description</i>	Proposed FSS Prices = 40% discount
		<i>Control Knobs</i>	
A-200	AKN01	Rebuild/Reseal angulation knobs	\$174.00
A-200	AKN02	Replace 40 series knob (branch)	\$156.00
A-200	AKN03	Replace U/D knob	\$351.00
A-200	AKN04	Replace R/L knob	\$351.00
A-200	AKN05	Replace both knobs	\$420.00
A-200	AKN06	Repair Elevator knob	\$174.00
A-200	AKN07	Replace angulation shaft	\$240.00
		<i>AL Tension Mechanism</i>	
A-200	ALT01	Reseal Ring	\$114.00
A-200	ALT02	Adjust AL	\$126.00
A-200	ALT03	Replace AL wire	\$132.00
A-200	ALT04	Replace AL collar	\$285.00
A-200	ALT05	Rebuild AL system	\$780.00
		<i>Angulation System</i>	
A-200	ANG01	Adjust Angulation Stoppers only	\$102.00
A-200	ANG02	Tighten and Adjust Stoppers	\$171.00
A-200	ANG03	Replace Stoppers	\$132.00
A-200	ANG04	Repair Angulation Slide	\$186.00
A-200	ANG05	Replace Angulation Wire x 4 (Pentax)	\$666.00
A-200	ANG06	Replace Coil Pipe	\$666.00
A-200	ANG07	Replace Coil Pipe Assembly	\$930.00
A-200	ANG08	Reattach Coil Pipe	\$240.00
A-200	ANG09	Angulation Rebuild	\$960.00
A-200	ANG10	Replace Coil Pipe Assembly/Rebuild Ang Sys	\$1,230.00
A-200	ANG11	Clean and Lubricate Wire/Coil Pipe	\$420.00
A-200	ANG12	Replace Marty's Piece	\$120.00
		<i>Auxiliary Water</i>	
A-200	AUX01	Repair Auxiliary Channel	\$105.00
A-200	AUX02	Replace Auxiliary Channel	\$615.00
		<i>Air/Water System</i>	
A-200	AWC01	Repair A/W Channel	\$105.00
A-200	AWC02	Replace A/W Channel	\$615.00
A-200	AWN01	Repair A/W Nozzle	\$54.00
A-200	AWN02	Replace A/W Nozzle	\$69.00
		<i>Bending Rubber</i>	
A-200	BDR01	Replace Bending Rubber	\$114.00
A-200	BDR02	Replace Bending Rubber - Puncture Proof Policy (60 days)	\$0.00

<i>SIN</i>	<i>Item# / Repair Code</i>	<i>Repair Description</i>	Proposed FSS Prices = 40% discount
		<i>Bending Section</i>	
A-200	BDS01	Reround bending section	\$45.00
A-200	BDS02	Replace Mesh	\$270.00
A-200	BDS03	Rebuild Bending section (includes mesh and wires)	\$315.00
A-200	BDS04	Replace bending section	\$840.00
		<i>Elevator System</i>	
A-200	BIE01	Clean Elevator Arm	\$48.00
A-200	BIE02	Adjust Elevator	\$114.00
A-200	BIE03	Replace Elevator Hub Assembly	\$960.00
A-200	BIE04	Replace Elevator Wire	\$150.00
A-200	BIE05	Replace Push/Pull Bar	\$90.00
A-200	BIE06	Repair Elevator Port	\$126.00
A-200	BIE07	Replace Elevator Channel	\$720.00
		<i>Biopsy Channel</i>	
A-200	BIOP01	Clear biopsy channel	\$54.00
A-200	BIOP02	Replace biopsy channel (large diameter)	\$690.00
A-200	BIOP03	Replace biopsy channel (small diameter)	\$840.00
		<i>CCD and EC Connector</i>	
A-200	CCD01	Seal CCD lens	\$255.00
A-200	CCD02	Repair/Replace Lens Assembly	\$780.00
A-200	CCD03	Clean EC Connector	\$69.00
A-200	CCD04	Rewire EC Connector	\$390.00
A-200	CCD05	Rewire EC Connector - Pentax	\$210.00
A-200	CCD06	CCD Rewire	\$1,260.00
A-200	CCD07	Calibrate Pentax video image	\$750.00
A-200	CCD08	Replace board - Pentax (price based on availability of part)	Quote
		<i>Control Body</i>	
A-200	CNB01	Reseal Biopsy Port	\$63.00
A-200	CNB02	Replace Aux Water Retaining sleeve	\$243.00
A-200	CNB03	Replace Biopsy Port O-ring	\$21.00
A-200	CNB04	Tighten A/W Cylinder	\$57.00
A-200	CNB05	Reseal S-Cover	\$57.00
A-200	CNB06	Repair/Seal Control Body	\$144.00
A-200	CNB07	Replace S-Cover	\$390.00
A-200	CNB08	Replace Control Body Grip	\$390.00
A-200	CNB09	Replace control body sleeve	\$330.00
A-200	CNB10	Replace 160/180 control body plate	\$750.00
A-200	CNB11	Replace Control Body Housing	\$960.00
		<i>CO2</i>	
A-200	CO201	Repair/Reseal CO2 Port	\$57.00

SIN	Item# / Repair Code	Repair Description	Proposed FSS Prices = 40% discount
		Cover Glass	
A-200	CVG01	Reseal Light Guide coverglass	\$57.00
A-200	CVG02	Clean & Polish Light Guide coverglass	\$57.00
A-200	CVG03	Clean & Polish Image Guide lens	\$57.00
A-200	CVG04	Replace 1 Light Guide Coverglass	\$90.00
A-200	CVG05	Replace 2 Light Guide Coverglass	\$174.00
A-200	CVG06	Replace 1 Light Guide Coverglass - small diameter/Pentax	\$90.00
A-200	CVG07	Replace 2 Light Guide Coverglass - small diameter/Pentax	\$174.00
		C-Cover	
A-200	CVR01	Clean distal end assembly	\$57.00
A-200	CVR02	Reseal C-Cover	\$147.00
A-200	CVR03	Repalce C-Cover	\$210.00
		Drum Wire	
A-200	DWA01	Replace Drum wire (x 2)	\$315.00
		ETO	
A-200	ETO01	Repair ETO	\$270.00
A-200	ETO02	Replace ETO Pin	\$63.00
		Insertion Tube	
A-200	IST01	Patch Insertion Tube	\$90.00
A-200	IST02	Reround/Realign Insertion Tube	\$90.00
A-200	IST03	Install Boot Extender	\$240.00
A-200	IST04	Install Extended Boot Extender	\$210.00
A-200	IST05	Replace Insertion Tube	\$1,260.00
A-200	IST06	Replace Insertion Tube Boot cone	\$240.00
A-200	IST07	Recoat Insertion Tube	\$1,500.00
		Light Guide Bundle	
A-200	LGB01	Clean and Polish LG Bundle	\$75.00
A-200	LGB02	Replace Light Guide Bundle (Includes Bio/Suction Chann)	\$990.00
A-200	LGB03	Reattach LG Bundle	\$180.00
		Light Guide Connector	
A-200	LGC01	Reround/Reseal Light guide connector	\$57.00
A-200	LGC02	Reseal Connections	\$63.00
A-200	LGC03	Replace Connector Assembly	\$450.00
A-200	LGC04	Clean connector	\$150.00
		Light Guide Prong	
A-200	LGP01	Repair Light Guide Prong	\$90.00
A-200	LGP02	Tighten Prong	\$45.00
A-200	LGP03	Clean and Reseal Prong	\$57.00
A-200	LGP04	Tighten Rear mount	\$90.00

SIN	Item# / Repair Code	Repair Description	Proposed FSS Prices = 40% discount
		Light Guide Tube	
A-200	LGT01	Patch Light Guide Tube	\$90.00
A-200	LGT02	Reround Light Guide Tube	\$57.00
A-200	LGT03	Replace Light Guide Tube	\$780.00
A-200	LGT04	Replace Light Guide Tube Boot Cone (includes EC rewire)	\$390.00
		Objective Lens	
A-200	OBL01	Reseal OB Lens	\$57.00
A-200	OBL02	Repair Objective Lens	\$480.00
A-200	OBL03	Replace Objective Lens	\$720.00
		Ocular	
A-200	OCR01	Rebuild Ocular	\$210.00
A-200	OCR02	Replace Eyepiece	\$240.00
A-200	OCR03	Reseal Ocular	\$66.00
		Suction System	
A-200	SCY01	Replace suction cylinder	\$660.00
A-200	SCY02	Repair suction cylinder	\$270.00
A-200	SCY03	Tighten suction cylinder	\$57.00
A-200	SUC01	Replace suction channel	\$330.00
A-200	SUC02	Clear suction channel	\$63.00
		Video Buttons	
A-200	VCH01	Repair #1 Button	\$102.00
A-200	VCH02	Replace #1 Button	\$144.00
A-200	VCH03	Replace Pentax Video Button (all 3)	\$210.00
A-200	VCH04	Repair video buttons	\$108.00
A-200	VCH05	Replace video control head	\$315.00
A-200	VCH06	Replace video control head wires (LGT)	\$210.00
A-200	VCH07	Tighten video control head	\$45.00
		Fluid Removal	
A-200	DOS01	Level 1 Fluid	\$510.00
A-200	DOS02	LEVEL 2 FLUID	\$270.00
A-200	DOSO3	Level 3 Fluid	\$150.00
		Image Bundle	
A-200	IMG01	Replace Image bundle	\$1,380.00

Price caps: Large Diameter scopes

\$2600 = insertion tube replacement, light guide tube replacement, biopsy channel, angulation rebuild, bending rubber replacement.

\$2500 = insertion tube replacement, biopsy channel, angulation rebuild, bending rubber replacement.

\$1800 = angulation rebuild, biopsy channel, bending rubber replacement.

\$1600 = light guide tube replacement, light guide bundle replacement, suction channel replacement, EC rewire.

\$1400 = light guide tube replacement, suction channel replacement, Ec rewire.

\$1200 = Light guide bundle replacement, suction channel replacement, bending rubber replacement, adjust angles.

Price caps: Small Diameter scopes

\$2800 = insertion tube replacement, light guide tube replacement, biopsy channel, angulation rebuild, bending rubber replacement, Image bundle replacement.

\$2200 = Image bundle replacement, biopsy channel, ocular rebuild, bending rubber replacement.

\$2000 = insertion tube replacement, biopsy channel, angulation rebuild, bending rubber replacement.

\$1800 = angulation rebuild, biopsy channel, bending rubber replacement.

\$1600 = light guide tube replacement, light guide bundle replacement, suction channel replacement, EC rewire.

\$1400 = light guide tube replacement, EC rewire

\$1200 = Light guide bundle replacement, bending rubber, adjust angles.



Contract Holder

V797P-4128b